



## Alkalis Testing VPI Requirements

**VPI Corporation**  
3123 S. 9th Street  
P.O. Box 451  
Sheboygan, WI 53082-0451, U.S.A.  
920-458-4664 • Fax 920-458-1368  
www.vpiflooring.com

A pH testing is required if there is any evidence of excessive alkalis. A flakey, chalky, surface is an indication of alkalis. These must be removed using water. The clean slab must then be allowed to dry. (A pH pencil or litmus paper and deionized water, are commercially available, this can be used for these testing requirements). Please refer to the Adhesive & Substrate Properties chart for detail information on pH, MVER and RH limits.

Alkalis Testing-VPI Requirements 3-05-13



Green Flooring    Static Control Flooring    Vinyl Flooring    Rubber Flooring    Wall Base    Accessories